ENVIRONMENTAL PROTECTION AGENCY REGION II EDISON, NEW JERSEY 08817

6

REPLY TO ATTN OF:

2 SA-TEC

DATE: June 19, 1974

SUBJECT:

Laboratory Analysis - Ventron Corporation - June 7, 1974

TO:

Chief, Emergency Response Branch

EPA Lab Sample No.	Sample Source
33601	Collected from small pile of solid material, 3' deep x 2' x3' at Ventron Corporation
33602	Collected from small tanks 20' x 15' behind Bldg. 13A, Ventron Corporation
33603	Collected from drum behind Bldg. 9, Ventron Corporation
33604	Collected at well at storm water outlet from plant, Ventron Corporation
33605	Collected at pad behind Bldg. 16, Ventron Corporation
33606	Collected from small pile of powdery material (1 cu ft)
33607	Collected from Ventron Corporation — bottle containing a pesticide as per bottle label (Cd dimethyldithiocarbamate)
33608	Collected from concrete trough in front of Bldg. 16, 2" deep, 30-35" long and 1' wide, Ventron Corporation
33609	Collected from mud pile 10' x 2' x ½', Ventron Corp.
33610	Water sample collected above demolition site at Moonachie Rd., Ventron Corporation
33611	Sample of mud collected at a creek above Ventron plant site on Moonachie Rd.
33612	Sample of water collected from Berry's Creek below the Ventron plant site at bridge on Pagerson Plank Rd. near Marior Sani-Can.



(Metals by Atomic Absorption Spectrophotometry Except Where Otherwise Indicated)

EPA Lab	<u>Hg</u>	<u>Ag</u>	<u>Cd</u>	<u>Zn</u>	<u>Ni</u>	<u>Cu</u>	<u>Pb</u>	<u>Mn</u>	Emission Spec Scan
Sample No.	mg/1	mg/1	mg/1 ==	mg/1	mg/1	mg/1	mg/l	mg/1	Al,Mg,Fe
The state of the s	State of the production of the state of the	Against the second	·ya	A CONTRACTOR					
33602	50	51,413.41	< 0.1	的题。2 -17	- 2		<1	0.5	T
33604	15	1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1	0.12	3	<0.6	<0.6		0.4	×
33608	285		0.60		5	4.8		92	
	0.22	2 Juni					<1	0.8	*
33612	14	<2	/ <0.1 %	<0.6	€0.6	€0.6	<1	8	
"你说我们看到我们	The state of the s		Martin made all of which		Barton Ho	e de la companya de l			
		Paris Company				Mary Mary 1994 A. C.			
	THE WAY TO SHE							,	Emission
	<u>Hg</u>	<u>Ag</u>	<u>Cd</u>	<u>Zn</u>	<u>Ni</u>	<u>Cu</u>	<u>Pb</u>	<u>Mn</u>	Spec Scan
EPA Lab 震荡	A PARTY OF THE PARTY	Alger mile tights about	一种的红色	MANUS AND ASSOCIATION OF THE PARTY AND ASSOCIATION OF THE PARTY AND ASSOCIATION OF THE PARTY ASS	Ortow Bill	lation To the	<u> </u>	· —	
Sample No. %S	mg/kg	mg/kg 🐘 ı	ng/kg	mg/kg	mg/kg	mg/kg	mg/kg	mg/kg	A1,Mg,Fe
White I was approximate	Secretary and the second	erafigire a transpolitic	w Thinks downer	建筑的 种的"4"。		y Lieungs	ine i	1	**
33601	9,500	< 50 📜	,	155	35	220	95	400	*
33603 40.	2 ** **	< 100 ⋅		200,000	<30	<30	60 -	24	
33605	1,000,000	great and the second		加强特别的		"整理"			
33606	540	170	5	200,000	670	110	660	310	*
33607 16.	5 1,600	<100 110 Company (1985)	0,000 (·	< 30	<30 ∶	< 30 ,	80	10	
33609	17,700	180	43		. 190 🦟	70	70	2,400	. * <u>.</u>
33611	9.9	< 2	2.5	130	0.8	35	45	13	*
ه رُحَدُهِ حَلَيْهِ بِينِهِ الْمُعَالِيدِينِ الرَّبِيقِ أَرِّ حَجَّالًا ا	13.66 小野林子神也真是。	greet to the state of the	بالمهاوي والمراجع فأم	الله في و را وجوارة الهرا	الموراضية وقد إلا المراجعة الموران المراجعة المراجعة المراجعة المراجعة المراجعة المراجعة المراجعة المراجعة الم			•	

^{*}Major components in the residue > 1%.

EPA Sample 33605 contained visible metallic mercury along with dirt and sand particles adhering to the mercury.

EPA Sample 33603 was collected from a drum labelled ziram fungicide (zinc dimethyldithiocarbamate), therefore, elemental analyses for zinc and sulfur were performed.

% S found = 40.4 theoretical = 41.9

% Zn found = 20.0 theoretical = 20.7 EPA Sample 33607 was in a bottle labelled cadmium dimethyldithiocarbamate (CDDC), 10% wettable powder, Woodridge Chemical Corporation. Elemental analysis for cadmium and sulfur and IR analysis established its identity as a 35-46% wettable powder.

> % Cd found = 11.0 theoretical for 100% CDDC = 31.7

% S found = 16.5 theoretical for 100% CDDC = 36.1

The remainder of the sample is probably a clay material.

EPA Sample 33606, based upon emission spec. scan and atomic absorption spectrophotometry, visual inspection and ignition testing, appears to be a mixture of metallic oxides. The brown color is probably mostly due to iron oxides.

Francis T. Brezenski
Chief
Technical Support Branch